

HIGH PRESSURE COUPLERS AND FITTINGS

- ▶ Suitable for working pressures up to 700 bar
- ▶ Designed to ensure easy system connection and assembly

Model number	See picture	Description	Thread specification
HF7	1	Nipple	1/4" NPT male to 1/4" NPT male
HF8	5	Adaptor	1/4" NPT female to 1/4" NPT female
HF10	2	Elbow	%" NPT female to $%$ " NPT female
HF12	3	Equal tee	¾" NPT female
HF13	4	Cross	%" NPT female
HF14	5	Adaptor	%" NPT female to %" NPT female
HF15	5	Reducer	%" NPT female to ¼" NPT female
HF16	6	Elbow	%" NPT female to %" NPT male
HF17	1	Nipple	%" NPT male to $%$ " NPT male
HF19	1	Long nipple	%" NPT male to $%$ " NPT male
HF24	7	Adaptor	%" NPT male to %" BSP female
HF27	1	Nipple	1/4" NPT male to 3/8" NPT male
HF30	7	Reducer	%" NPT male to $1/4$ " NPT female
HF31	8	Tee	%" NPT female to %" NPT male
HF33	7	Reducer	$\%$ " NPT male to $1\!\!/\!4$ " BSP female
HF55	7	Reducer	%" NPT female to 1/4" NPT male
HF69	7	Adaptor	$\frac{1}{2}$ " BSP male to $\frac{3}{6}$ " NPT female
CF1	9	Female coupler	%" NPT male
СМ1	10	Male coupler	%" NPT female
CMF1	9 + 10	Complete coupler	3/8" NPT
CF2	9	Female coupler	1/4" NPT male
СМ2	10	Male coupler	1/4" NPT female
CMF2	9 + 10	Complete coupler	1/4" NPT
CFD1	11	Metal dust cap for CF1	
CMD1	12	Metal dust cap for CM1	
CFD2	11	Metal dust cap for CF2	
CMD2	12	Metal dust cap for CM2	
PPC1	13	Moulded universal dust cap to suit CF1 & CM1	



Picture 1



Picture 2



Picture 3



Picture 4



Picture 5



Picture 6



Picture 7



Picture 8



Picture 9



Picture 10



Picture 11



Picture 12



Picture 13